
Type 03 Category: Facade elements

Window apron walls


Subtype n°14, dimensions 1:50






Connection

1:20





Type 03 Category: Facade elements

Window apron walls

| Description | | | | Condition and durability | |
|---------------------|---|----------------|----------------------|--------------------------------|---------------------------|
| Exposition | Outdoor, exposed to rain and water flow | | Condition assessment | 43 % good | |
| Color | Grey with a yellowish tint, | closest RAL 70 |)44 | | 54 % acceptable |
| Finishing | Horizontal wood plank pat | terns | | | 3 % deviant |
| Actual location | E, W and S facades | | | Carbonatation depth [mm] | Avg. 2-16 (max 19) |
| Initial function | Facade self-supporting element | | Toxic substance | PCB; asbestos | |
| Accessibility | Moderate – One/two eler | ments to disma | antle before | | |
| Anchor points | Not available | | | Mechanical characteristics | |
| Overlays | Туре | Fixation | Thickness | Density | 2500 kg/m³ |
| From concrete | Mortar | - | 5 mm | Concrete compressive strength | 41 N/mm ² |
| | Cork | Glued | 30 mm | Concrete young modulus | 38'600 N/mm ² |
| | Plaster | - | 10 (ev. 5) mm | Reinforcement tensile strength | 450 N/mm ² |
| To surface | Wallpaper (or painting) | - | - | Reinforcement young modulus | 205′000 N/mm ² |
| Connexion type | Connected to other facade | e elements and | d to slabs | | |
| Deconstruction tool | To facade elements | To slab | | | |
| | Diam. saw | Diam. Saw | or hydro-blasting | | |

| Element | Ge | eometry | | | | Inventory | l | | | nmental acts |
|----------------|----------------------------|--------------------|--------------------------------|--------------|---------------|-----------------|-------------------|--------------|------------------------------------|---|
| N° | Dimensions (WxLxT) [mm] | Reinforcement [mm] | Cross-section resistance [kNm] | Quantity [u] | Weight [kg/u] | Total area [m²] | Total volume [m³] | Significance | Initial production [kgC02-eq/u] | Conventional demolition [kgCO2-eq/u] |
| 39 | 1380 x 1280 x 160 | Ø 4 S = 100-150 | 6,2 - 4,2 | 72 | 706,5 | 127,2 | 20,3 | 0,3% | 63 | 7 |
| 14, 34, 35, 96 | 3195 x 1280 x 160 | Ø 4 S = 100-150 | 6,2 - 4,2 | 420 | 1636 | 1717,6 | 274,8 | 4,0% | 146 | 16 |
| 11, 30, 31 | 3235 x 1280 x 160 | Ø 4 S = 100-150 | 6,2 - 4,2 | 117 | 1656 | 484,5 | 77,5 | 1,1% | 147 | 17 |
| 95 | 3250 x 1280 x 160 | Ø 4 S = 100-150 | 6,2 - 4,2 | 9 | 1664 | 37,4 | 6,0 | 0,1% | 148 | 17 |
| 15, 17, 36, 38 | 3415 x 1280 x 160 | Ø 4 S = 100-150 | 6,2 - 4,2 | 78 | 1748 | 341,0 | 54,6 | 0,8% | 156 | 17 |
| 91, 92, 93, 94 | 3420 x 1280 x 160 | Ø 4 S = 100-150 | 6,2 - 4,2 | 18 | 1751 | 78,8 | 12,6 | 0,2% | 156 | 18 |
| 13, 16, 33, 37 | 3425 x 1280 x 160 | Ø 4 S = 100-150 | 6,2 - 4,2 | 78 | 1759 | 342,0 | 54,9 | 0,8% | 157 | 18 |
| 10, 12, 2, 32 | 3440 x 1280 x 160 | Ø 4 S = 100-150 | 6,2 - 4,2 | 78 | 1761 | 343,4 | 55,0 | 0,8% | 157 | 18 |

| Type 03 | Category: Facade elements |
|--------------------|---------------------------|
| Window apron walls | |

| Additional note | > The carbonatation depth is lower than the 20-mm concrete cover of the rebars. |
|-----------------|---|
| | > The depth of carbonatation is less important for the elements of the southern facade. |
| | > For horizontal storage of the window apron walls, support spacers should be placed every 2.8 m, and the outdoor side should be facing downwards. |
| Attention point | > The waterproofing joints sealant placed between the facade elements probably contain polychlorinated biphenyls (PCB). These joints must be completely removed by a specialized company. The removal can be done with a cutter, while avoiding heating the joints or producing dust. |
| | > Contamination with PCBs of the concrete neighboring the joints should be checked by further sampling. Most probably, it will be necessary to remove 1cm of the edge that was in contact with the joint. |
| | > The cork is tested negative in the four sampling areas to polycyclic aromatic hydrocarbon (PAH) but should be handled with care. |
| | > Asbestos was detected in some of the plaster covering. |

